

Status of RF Group HZB

(former BESSY)

Wolfgang Anders




Outline:

- BESSY + HMI = HZB
- Low level
- Klystrons ~ 80.000 h
- HV part burned
- IOT instabilities
- RF leakage on klystron

HMI + BESSY = HZB

Berlin






- Low α optic, terahertz radiation and infrared users are limited by the noise of the transmitters.
- We are now evaluating, if we need new low level system
- New master clock R&S SMA 100A with frequency resolution of 0.01 Hz for more precise horizontal orbit correction
- Noise at master clock ~ 70 fs \rightarrow after 200 m cable ~ 500 fs

80.000 h klystrons

3 of 4 klystrons at BESSY II have
operating time of ~ 80.000 h now




Coaxial switch at
the 75 kW RF line




To be prepared in case of
problems, we install a high
power coaxial switch with load at
each transmitter.

HV PS defekts



Burned part in HV PS

**Broken brass rod at
HV transformer**



Last year I reported on IOT phase/amplitude instabilities on E2V and CPI IOT

Planned measurements for near future:

- Measurements at Thales IOT 1.3 GHz
- Repeat measurements after 1 year of operation on CPI 80 kW 500 MHz IOT at MLS
- Measurements on CPI klystron

Curios: energy saving lamp



RF leakage at 10 kW 1.3 GHz klystron

→ Operating a neon lamp „without energy“
at RF field of 15 V/m in air

Thank You

