

13th ESLS RF Meeting - 1st October 2008

80 kW/at Damp Francis Perez

DAMPY Cavity 1/20



- Reminder
- Dampy 01
- Dampy 00 Bridged
- Dampy 01 Repaired
- Dampy 02 & 03
- Measurements
- Next

November 08

January 09


April 09


September 09



Flange local overheating

which develops in a vacuum leak






DAMPY Cavity 3/20




<u>Solutions</u>

1) Thick RF Gasket to short cut the RF path

Soft Copper gasket




2) Flange modification with added Copper



DAMPY Cavity 4/20

Dampy 01 in November 2008




Even worse overheating, 50°C at 15 kW!! Leak at less than 20 kW

DAMPY Cavity 5/20



Dampy 01 in November 2008

Two problems detected:



Overfloading welding material



Figure 1: Cavity flange for top-damper. Good quality.




Figure 2: Cavity flange for window damper. Bad quality: bumpy



Approach followed

1) Sent back to ACCEL to:

Remachine flange's step to a defined dimension:




2) Power tests again Dampy 01 after repair

3) Decide then if apply the same solution at the rest of cavities

But in the mean time...



SR Dampy 00-B (Bridged)




DAMPY Cavity 8/20



SR Dampy 00-B , January 2009

Successful power test up to 60 kW




But still temperatures high, 55°C at 60 kW!!

DAMPY Cavity 9/20



SR Dampy 00-B , January 2009

But, after <u>ten</u> 60 kW cycles... a small vacuum leak developed in the same spot



because the bridge is not 100% effective and <u>no RF gasket</u> was installed


DAMPY Cavity 10/20



13th ESLS RF Meeting – 1st October 2008

Dampy 01 (repaired) in April 2009

- We performed extra quality checks
 - Measure the gap
 - Check all the weldings
 - Check the installation of the gaskets












Dampy 01 (repaired) in April 2009




The 21st of April, 10 cycles at 60 kW, with maximum temperature < 40°C

DAMPY Cavity 12/20



Dampy 01 (repaired) in April 2009




The 23rd of April, 80 kW with maximum temperature 41°C

We decided to make the same modification on the rest 5 cavities



Dampy 02 & 03 tested in September 2009




DAMPY Cavity 14/20

Auto Conditioning

- ✓ Implemented in the Digital LLRF, in each RF plant
- ✓ Amplitude and duty cycle depending on vacuum levels
- ✓ Amplitude increase rate (slope): adjusted by operator
- ✓ Vacuum signal connected to LLRF






■ Vacuum < Limit Down → Voltage Amplitude Increases/Decreases</p>

• Vacuum > Limit Up \rightarrow Voltage Amplitude remains constant until vacuum is below limit down



Auto Conditioning




From 0 to 70 kW in ~16 hours




Fast Data Logger

- ✓ Implemented in the Digital LLRF, in each RF plant
- ✓ All RF signals of the RF plant
- ✓ Triggered by the Fast Interlock Unit
- ✓ Store up to 400 ms at 5 MHz sampling per channel











Radiation measurements (Safety Group)



At 80 kW: Dose Rate up to 15 mSv/h XR energy up to 600 keV






NEXT STEPS

- Conditioning in RF Lab
 - Dampy 04
 - Dampy 05
 - Dampy 06
- Installation in the ring in March 2010.

THANK YOU






DAMPY Cavity 21/20



LLRF (new implementations into the FPGA)

Booster Field flatness loop

Automatic Conditioning




DAMPY Cavity 22/20



Manual Conditioning - 1st October 2008

RF Drive square modulated

- ✓ Duty Cycle of pulses adjustable (1-100%)
- ✓Amplitude adjustable
- ✓Time between pulses = 100ms (10Hz)
- \checkmark Tuning Loop only enable at top of the pulses



Drawbacks

- ✓ Operator needed to adjust amplitude and duty cycle
- ✓ Vacuum levels not considered by LLRF → frequent interlocks