

RF Status of ALBA

Angela Salom on behalf of RF team: Francis Perez, Bea Bravo and Jesus Ocampo

00

✓ ALBA RF Overview: Booster and SR

Outline

- ✓ RF Operation with beam
 - Statistics of RF operation
 - RF Incidents

-BA

- Spring Shutdown
- RF Upgrades: Costubs and cooling
- ✓ Future RF upgrades
 - Feedforward loops



Booster RF Plant

Ramping from 100MeV to 3GeV at 3Hz




	Injection	Extraction
Cavity voltage 55kV		1000kV
Energy loss	0.001keV/turn	627keV/turn
Cavity power	0.1kW	33kW
Beam Power	0kW	2.5kW
Sync. Freq	13.7kHz	9.4kHz

Petra Cavity type (5 Cells) Normal Conducting 500MHz 80kW CW - IOT

Booster: Operation without major incidents

Storage Ring RF Plants





- 6 RF Plants of 160kW at 500 MHz
- 2 IOT Transmitters per RF cavity. Power combined in CaCo

```
Dampy Cavity
Normal Conducting
Single cell, HOM damped
3.3 MΩ
```

Digital LLRF System based on IQ mod/demod







Run #	IOTs body currents	Water ITCKS	others (arcs, reverse , vacuum)	total
1	38	11	12	61
2	23	12	20	55
3	28	64	51	143

Run #	RF Failures producing beam dump (%)	Total beam hours	Downtime due to RF failures (h)
1	24.6%	443.5	5
2	14.5%	461.9	6
3	10.5%	652	7.2

 ✓ Many RF Trips, but most of them do not have impact on operation
 ✓ Fast recovery of faulty RF Plants




IOTs status

Serial #	FIL (h)	HV (h)
499443	16793	11467
617551	12733	9887
747211	new	new
623096	13213	9373
720105	4361	3461
634238	12042	9849
617302	14016	10231
617302	14523	10472
617549	4616	3762
793734	14272	10107
620408	1714	1087
720785	13949	10715
623099	14094	10699
	499443 617551 747211 623096 720105 634238 617302 617302 617549 793734 620408 720785	4994431679361755112733747211new623096132137201054361634238120426173021401661730214523617549461679373414272620408171472078513949

	Broken Tubes	FIL (h)	HV (h)	Comment
	608802	10627	7585	
	617550	10290	6970	
	629734	7828	5080	
	610735	7408	4815	Water leak
	610732	4221	3324	
	499413	1639	1101	First IOT installed
/	623097	2316	515	

✓ 13 IOTs: 1 Booster – 12 SR

- 9 old IOTs. FIL~ 14000h, HV ~ 9200h
- Degradation observed in some of them. At low power:
 - New IOTs grid current < 10mA.
 - Old IOTs grid current > 30mA



✓ Statistics of broken IOTs

IOT average life: FIL ~ 6400h, HV ~4200h



Main RF Incidents


✓ 1st run: 14th Jan – 16th Feb

2 IOTs got broken (Fil hours

✓ 2nd run: 25th Feb – 22nd March

- 2 circulators got broken
 - First one: Water leak in c
 - Second one: short-circuit
- 2 Brand New IOTs got broke the ceramic. Thales providec







ALBA

Main RF Incidents

- During Spring Shutdown: Loops of CaCo got broken when installing short-circuit
 - CaCo Symmetric mode: Combines power of two IOTs
 - CaCo Asymmetric mode: one IOT is switched off while 2nd IOT is active



All loops of CaCo had to be reviewed and replaced during summer shutdown



 Air in the cooling system made the pressure drop steadily causing the accelerators sub-systems to trip.

Spring Shutdown

✓ Cooling Improvements

General pipes of cooling system were cleaned (sponges found in the process)






- Water pumps operation conditions changed to avoid cavitation
- Flow Control and distribution optimized
- Air purging
- Air releasers installed in whole machine


ALBA

Spring Shutdown

 ✓ After solving cooling problem, cooling control PLC misconfiguration error stopped heater exchanger operation and water temperatures rose above 50°



- High temperatures damaged cooling hoses of power supplies
- One hose got broken a couple of days later → Power supply got damaged
- All PS cooling hoses had to be replaced



RF Operation: Main Error Sources

✓ Body currents of IOTs – 50% of RF Interlocks per run

- 80-90% of these body current interlocks located in the same IOTs (2 or 3)
- "Bad" IOTs combined together in the same plant and working at lower power
- IOTs conditioning (20% pulse mode 20-30kW) every Monday morning (machine shutdown)

✓ Cooling system – 20% of RF Interlocks per run

- Water Flow Meters of IOTs (WFM) sampling rate is 0.5s.
- Monitoring WFM analogue data, we found out that randomly some WFM samples were lost and WFM digital output went to interlock state during 0.5s
- Delay relays added to the digital output of WFM. If interlock lasts less than 0.7s, it is disregarded → Since then, no IOT cooling interlocks

✓ Other kind of error sources

- Two absorbers replaced during 2013: cavities had to be reconditioned. Many interlocks during last run due to reverse power interlocks
- Radiation: Some electronic boards placed inside tunnel got damaged and produced fake temperature interlocks

ALBA

RF upgrades


During Summer Shutdown, Costubs installed in all IOTs of SR and CaCo Loops replaced


- Change between symmetric and asymmetric mode has become very fast (less than 10 minutes)
- ✓ Very helpful for analyzing IOT problems independently



Future RF upgrade

Feedforward loop to compensate transient when RF cavity trips






✓ When cavity trips

- Cavity Voltage oscillates with frequency equal to synchrotron tune
- Transient time equal to damping time of machine

✓ Compensation

- Amplitude modulation triggered when one cavity trips
- Frequency, amplitude and phase of modulation are adjustable parameters

✓ Tests with beam still pending





Summary & Conclusions

- ✓ Next year can only be better!
- ✓ Costubs allow much faster recovery of RF plants when an IOT is down
- ✓ IOTs cooling interlocks upgrade has improved statistics
- ✓ RF robust enough for operation at 120mA

Acknowledgments

✓ RF team: Francis Perez, Bea Bravo, Jesus Ocampo, Joan Pijuan and Pol Solans.

✓ Operators, technicians and controls support

Thanks for your attention

Ancillary slides: Phase jump in 14B

